Prepared (also subject responsible if other)		No.		
EBC/KCM/D Yvonne Bergström		109 21-DPA 200 32/1-2 Uen		
Approved	Checked	Date	Rev	Reference
EBC/KCM/DP (L-E Gustavsson)		2008-02-01	A	

Document category:	Document No.:	R-state	from	to
Circuit Revision Information	1/109 21-		See	below
Material Revision Informaion	2/109 21-			
Wiring Revision Information	3/109 21-			
Revision state of product documents after revision, see 1095-				

DT422 V2 Cordless Phone

1 Reason for revision

New functionality and corrections.

1.1 New Functionality

a An LCD contrast adjustment. A contrast settings menu is introduced.

b The beep volume for “no system warning” is increased and the beep is repeated.

c Headset button has new functions as:
- Go off hook
- Go off hook and trigger a Hot Key
- Reset the Man Down/No Movement pre-alarm also when the Phone Lock is active

d TPE plug for headset connector is not mounted on the handset any longer

1.2 Corrections

a Call waiting signal during call using IP-DECT

Translation errors solved. MX 196 405

2 Technical solution

Software revision is changed from 3.28 to 3.43

3 Products concerned

- DPA 200 32/1 changed from **R1E** to **R1F**
- DPA 200 33/1 changed from **R1E** to **R1F**

Prepared (also subject responsible if other)		No.		
EBC/KCM/D Yvonne Bergström		109 21-DPA 200 32/1-2 Uen		
Approved	Checked	Date	Rev	Reference
EBC/KCM/DP (L-E Gustavsson)		2008-02-01	A	

4 Recommended measures

It is recommended to introduce the revision where the problem described under reason for revision occurs and in new manufacturing.

For products in field, new software can be found on the knowledge data base and downloaded in the cordless phone.

IMS versions older than 2.62 are incompatible and can not be used. Using an IMS with older software than 2.62 will result in loss of messages longer than 420 digits. This can be the case for example when using the central phone book function.

For optimum Quality of Service IMS version 2.73 or later shall be used.